

ORIG
UNIT
EXT
DATE

25 SEPT 1963

S-E-C-R-E-T

COMMO/OSA

AD/OSA

D/PA/OSA

OS/OSA

INTEL/OSA

TO/OSA

DEFERRED

PRIORITY

IMMEDIATE

00121235

3845

TO

FROM: DIRECTOR

CONF:

INFO

OSA 1-15

EDD

WER

RDO

RLP

KB

SHI

PGS

TO

INFO

TO

IDEALIST COMMO

ODINCH TECH FEEDBACK

PERFORMANCE MSN 6066 FOLLOWS:

1. TRACK 1; NORMAL SCAN, NORMAL DWELL. NOISE LEVEL LOW, GOOD INTERCEPTS.
2. TRACK 2; NOISE LEVEL LOW. DWELL TIMES ONLY MOMENTARY, PREVENTING GOOD INTERCEPT READOUT. SCAN ERRATIC FOR 1.5 HRS AFTER TAKEOFF, THEN NORMAL UNTIL 1 HR BEFORE LANDING WHEN SCAN AGAIN ERRATIC.

3. TRACK 3; NOISE LEVEL LOW, DWELL TIME 10-15 SECS. VISION GOOD QUALITY, MANY INTERCEPTS. SCAN REPORTED AS ERRATIC.

4. HQS COMMENT: FYI, [] ANALYZED [] TAPE FOR MSN 6066, AND SUPPORTED [] CONTENTION THAT SCAN ALL TRACKS NORMAL. [] IN FACT, [] COMMENTED ON THE FINE QUALITY ACHIEVED USING THE NEW MMM 490 TAPE IN THE [] CONTINUING ATTEMPTS RESOLVE NATURE OR CAUSE OF "ERRATIC SCAN". [] WILL ACCOMPANY STL TECH [] REP TO ODINCH 27 SEPT INVESTIGATE POSSIBILITY OF MALFUNCTIONING READOUT EQUIPMENT. WILL ADVISE.

25 YEAR RE-REVIEW

END OF MESSAGE

COORDINATING OFFICERS

A/CHIEF, COMMO/OSA

RELEASING OFFICER

S-E-C-R-E-T

AUTHENTICATING OFFICER

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED

Copy No.